



海軍大氣海洋局航船布告

中華民國107年11月1日

64 (暫) 金門海域 — 燈浮流失、光力減弱及暫停發光

依據 交通部航港局中部航務中心107年10月25日第1073201386A號航船布告。
說明 金門航道燈浮流失、光力減弱及暫停發光，航行船隻，請多加注意。
位置 1. (C3) 北緯24°30'08.8"，東經118°20'00.7" (流失)
2. (B2) 北緯24°25'39.8"，東經118°17'03.8" (光力減弱)
3. (JT6) 北緯24°27'08.3"，東經118°16'47.0" (光力減弱)
4. (JT9) 北緯24°28'24.1"，東經118°16'34.7" (燈光熄滅) (WGS84)
海圖 04526 - 0319A
刊物 燈表 106年第十一版(刊物第五種), 52170 - 52210 - 52240 - 52270

海軍大氣海洋局局長
海軍上校 崔怡楓

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Nov-1-2018

64 (T) Kinmen Waters – Buoy Lost, Light Weakened and Temporarily Stop Functioning

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1073201386A dated October 25, 2018.
Details Light-buoys, located in Kinmen channel, had been lost, light weakened and extinguished. Mariners should navigate with caution in this area.
Position 1. (C3) 24°30'08.8"N., 118°20'00.7"E. (Lost)
2. (B2) 24°25'39.8"N., 118°17'03.8"E. (Light weakened)
3. (JT6) 24°27'08.3"N., 118°16'47.0"E. (Light weakened)
4. (JT9) 24°28'24.1"N., 118°16'34.7"E. (Light extinguished) (WGS84)
Chart affected 04526 - 0319A
Publication affected Pub. No.5 List of Lights (Edition 11, 2017), buoys No. 52170 - 52210 - 52240 - 52270

CAPT. I-Fong Tsui
Commanding Officer, NMOO