



海軍大氣海洋局航船布告

中華民國112年2月10日

19 (暫) 新竹外海 — 警示燈故障

依據 交通部航港局中部航務中心112年1月31日中技字第1120051259A號函。
說明 下列位置之風機警示燈故障，修復後將另行通知，航經該水域船隻請多加注意。
位置 北緯 24°42'45.9"，東經 120°50'05.5" (#04)
北緯 24°41'58.2"，東經 120°49'35.9" (#14)
北緯 24°41'35.8"，東經 120°49'01.5" (#21)
北緯 24°41'27.6"，東經 120°48'24.1" (#28) (WGS84)
海圖 04510 - 04511 - 0356

海軍大氣海洋局局長
海軍上校 孫永大

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Feb-10-2023

19 (T) Hsinchu Offshore – Warning Light Damaged

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1120051259A dated January 31, 2023.
Details WTG warning lights at the following positions had stopped functioning due to the damage, and further notice will be issued while fixed. Mariners are advised to navigate with caution in this area.
Position 24°42'45.9"N., 120°50'05.5"E. (#04)
24°41'58.2"N., 120°49'35.9"E. (#14)
24°41'35.8"N., 120°49'01.5"E. (#21)
24°41'27.6"N., 120°48'24.1"E. (#28) (WGS84)
Chart affected 04510 - 04511 - 0356

CAPT. Yung-Da Sun
Commanding Officer, NMOO