

# 海軍大氣海洋局航船布告

## NOTICE TO MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

第 6 號

No.6 of 2017

### 臺灣海域

### Taiwan Waters

#### 高雄港西部海域 — 貨輪沉沒

#### Kaohsiung Harbor West Waters – Cargo ship Sank

- 位置 (A)北緯 22°29'00.0"，東經 119°41'00.0"。(概位)(WGS84)  
 (B)北緯 22°26'00.0"，東經 119°44'00.0"。(WGS84)  
 (C)北緯 22°29'00.0"，東經 119°42'00.0"。(WGS84)
- 說明 1. 106年1月14日1718時，中國大陸籍「通成601」貨輪，  
 在上述位置(A)沉沒，海上漂流20只貨櫃。  
 2. 106年1月15日0720時，在上述位置(B)發現1只貨櫃。  
 3. 106年1月15日0820時，在上述位置(C)發現油污(長2  
 哩，寬50-100公尺)，向南漂流。  
 4. 航行船隻，請多加注意。
- 關係圖書 普通海圖第 0338, 0313, 0013 號。  
 根據 交通部航港局南部航務中心106年1月15日航船布告(海巡  
 署106年1月15日署勤電字第089號傳真)。  
 備註 本局航船布告網址：<http://navy.mnd.gov.tw>

- Positions - (A) Lat.22°29'00.0"N., Long.119°41'00.0"E. (PA)(WGS84)  
 (B) Lat.22°26'00.0"N., Long.119°44'00.0"E. (WGS84)  
 (C) Lat.22°29'00.0"N., Long.119°42'00.0"E. (WGS84)
- Details - 1. A Cargo ship, *Tong Chen 601*, sank at the above position  
 (A) and 20 containers for overboard at 1718hrs, January  
 14<sup>th</sup>, 2017.  
 2. One container for overboard at the position (B) at  
 0720hrs, January 15<sup>th</sup>, 2017.  
 3. Southward oil spill drifting (2 nautical miles length,  
 50-100 meters width) was discovered at the position (C)  
 at 0820hrs, January 15<sup>th</sup>, 2017.  
 4. Mariners are advised to navigate with caution in this  
 area.

Chart affected - NMOO Charts 0338, 0313, 0013.

Source - South Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, Notice to Mariners dated January 15<sup>th</sup>, 2017 (Coast Guard Administration facsimile dated January 15<sup>th</sup>, 2017.)

Remarks - Notice to Mariners Website: <http://navy.mnd.gov.tw>

中華民國 106 年 1 月 16 日

海軍大氣海洋局局長  
海軍上校 崔怡楓

CAPT I-Fong Tsui  
Commanding Officer, NMOO  
Zuoying, Taiwan,  
Republic of China