



海軍大氣海洋局航船布告

中華民國107年3月19日

13 (暫) 龍門及尖山漁港 — 導燈暫停發光

依據 臺灣港務股份有限公司高雄港務分公司107年3月12日高港馬公字第1073251031號函。
說明 澎湖龍門及尖山漁港之導燈進行維修暫停發光，修復後另行公告，航行船隻，請多加注意。
位置 北緯23°33'34.9"，東經119°40'20.0"
北緯23°33'43.0"，東經119°40'20.1" (WGS84)
海圖 61709 - 04525 - 04529 - 0331 - 0336
刊物 燈表 106年第十一版(刊物第五種) 51150 - 51160

海軍大氣海洋局局長
海軍上校 崔怡楓

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Mar-19-2018

13 (T) Longmen and Jianshan Fishery Harbor – Leading Beacons Temporarily Stop Functioning

Source Port of Kaohsiung, Taiwan International Ports Corporation Ltd., letter No. 1073251031 dated March 12, 2018.
Details Longmen and Jianshan Fishery Harbor leading beacons temporarily stop functioning and repairing work is in progress. It will be resumed in further notice after finished. Mariners should navigate with caution in this area.
Position 23°33'34.9"N., 119°40'20.0"E.
23°33'43.0"N., 119°40'20.1"E. (WGS84)
Chart affected 61709 - 04525 - 04529 - 0331 - 0336
Publication affected Pub. No.5 List of Lights (Edition 11, 2017), beacon No. 51150 - 51160

CAPT. I-Fong Tsui
Commanding Officer, NMOO