



海軍大氣海洋局航船布告

中華民國107年10月22日

62 (暫) 安平燈塔暫停發光

依據 交通部航港局航安組107年10月19日第L10710005號航船布告。
說明 1. 據報安平燈塔已暫停發光，修復後即照常發光，屆時不另公告，航行船隻，請多加注意。
2. 施工時間：即日起至107年11月23日。
3. 欲知修復進度，請逕洽交通部航港局航安組(電話：02-89786805)。
位置 北緯22°59'26.7"，東經120°08'49.1" (WGS84)
海圖 61001 - 04505 - 04506 - 0336
刊物 燈表 106年第十一版(刊物第五種), 30210

海軍大氣海洋局局長
海軍上校 崔怡楓

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Oct-22-2018

62 (T) Anping Lighthouse Temporarily Stop Functioning

Source Maritime Safety Division of the Maritime and Port Bureau, MOTC, notice to mariners No. L10710005 dated October 19, 2018.
Details 1. It's reported that Anping lighthouse had stopped functioning. It will be resumed without further notice while fixed. Mariners should navigate with caution in this area.
2. Work period : Until November 23, 2018.
3. Contact to the Maritime Safety Division (Tel:886-2-89786805) for the latest information.
Position 22°59'26.7"N., 120°08'49.1"E. (WGS84)
Chart affected 61001 - 04505 - 04506 - 0336
Publication affected Pub. No.5 List of Lights (Edition 11, 2017), lighthouse No. 30210

CAPT. I-Fong Tsui
Commanding Officer, NMOO