



## 海軍大氣海洋局航船布告

中華民國110年3月5日

### 33 (暫) 臺灣西部海域 — 基樁新設及燈質修正

依據 交通部航港局中部航務中心110年2月18日中技字第1103250563A號函。

說明 1. 編號YUN38及YUN80基樁佈放完成，頂部架設警示燈。  
2. 編號YUN53基樁燈質修正。  
3. 航經該水域船隻請注意避讓。

位置 詳如附件。

海圖 04507 - 0336

參考布告 109年第113(暫)號航船布告。

海軍大氣海洋局局長  
海軍上校 孫永大

### NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Mar-5-2021

### 33 (T) Taiwan West Waters – Monopile Installed and Characteristic Changed

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1103250563A dated February 18, 2021.

Details 1. #YUN38 and #YUN80 monopiles have been installed with a warning light on the top.  
2. #YUN53 monopile characteristic changed.  
3. Mariners are advised to navigate with caution in the area.

Position See attachment.

Chart affected 04507 - 0336

Reference Former Notice 113(T)/2020.

CAPT. Yung-Da Sun  
Commanding Officer, NMOO

附件  
Attachment

NM 33

基樁編號 Monopile No.	位置 Position (WGS84)	燈質 Characteristic	見距 (浬) Range (mile)
YUN38	23°35'58.9"N. 120°03'08.5"E.	黃閃光2.5秒 Fl.Y.2.5s	2
YUN80	23°33'23.2"N. 120°01'51.5"E.	黃閃光2.5秒 Fl.Y.2.5s	2
YUN53	23°34'12.4"N. 120°02'09.0"E.	黃閃光2.5秒 Fl.Y.2.5s	2