



海軍大氣海洋局航船布告

中華民國110年4月6日

49 (暫) 麥寮港 — 塔身修繕工程

依據 交通部航港局中部航務中心110年3月26日中技字第1103200421A號函。
說明 即日起至110年9月30日止，進行麥寮港西、南堤燈塔塔身修護工程，施工期間因圍設鷹架，影響燈塔日間辨識但不影響夜間燈質，航經該水域船隻請注意安全。
位置 北緯23°46'50.1"，東經120°09'04.0"
北緯23°46'46.5"，東經120°09'40.0" (WGS84)
海圖 0361A - 0361
刊物 中華民國燈表(109年第12版, 刊物第五種), 編號：23030、23040

海軍大氣海洋局局長
海軍上校 孫永大

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Apr-6-2021

49 (T) Mailiao Harbor – Overhauling of Beacon External Wall

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1103200421A dated March 26, 2021.
Details W. and E. breakwater beacon located in Mailiao harbor is under overhauling until September 30, 2021. Beacon daytime identifying is affected by scaffold during this period, but it is clear at night. Mariners are advise to navigate with caution in this area.
Position 23°46'50.1"N., 120°09'04.0"E.
23°46'46.5"N., 120°09'40.0"E. (WGS84)
Chart affected 0361A - 0361
Publication affected Pub. No.5 List of Lights (Edition 12, 2020), No. 23030, 23040

CAPT. Yung-Da Sun
Commanding Officer, NMOO