



海軍大氣海洋局航船布告

中華民國 106 年 11 月 3 日

91 (暫) 基隆島燈塔暫停發光

依據 交通部航港局航安組 106 年 11 月 1 日第 L10611003 號航船布告。
說明 1. 據報基隆島燈塔已暫停發光，修復後即照常發光，屆時不另公告，航行船隻，請多加注意。
2. 欲知修復進度，請逕洽交通部航港局航安組(電話：886-2-89786805)。
位置 北緯 25°11'33.9"，東經 121°47'13.1"。(WGS84)
海圖 0353A - 0353 - 04513 - 04514 - 0352
刊物 燈表 101 年第十版(刊物第五種) 11160

海軍大氣海洋局局長
海軍上校 崔怡楓

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

November 3, 2017

91 (T) Keelung Islet Lighthouse Temporarily Stop Functioning

Source Maritime Safety Division of the Maritime and Port Bureau, MOTC, notice to mariners No. L10611003 dated November 1, 2017.
Details 1. Keelung islet lighthouse is reported stopped functioning. It will be resumed without further notice. Mariners should navigate with caution in this area.
2. Contact to the Maritime Safety Division (Tel:886-2-89786805) for the latest information.
Position 25°11'33.9"N., 121°47'13.1"E. (WGS84)
Chart affected 0353A - 0353 - 04513 - 04514 - 0352
Publication affected Pub. No.5 List of Lights (Edition 10, 2012), lighthouse No. 11160

CAPT. I-Fong Tsui
Commanding Officer, NMOO