




海軍大氣海洋局航船布告

中華民國108年10月7日

49 南方澳漁港 — 海圖訂正

依據 1. 108年10月1日交通部航港局航船布告。
2. 108年10月3日海軍大氣海洋局實測水深資料。

說明 1. 南方澳跨港大橋塌後新測水深更新。
2. 請將附件貼圖剪貼在本局出版之海圖(0351A)上。
3. 請將「警戒區」標註在本局出版之海圖(04515、04516)上。

符號  (海圖04515、04516) 北緯24°35'10.9"，東經121°52'07.4"
北緯24°35'10.9"，東經121°52'12.9"
北緯24°35'07.1"，東經121°52'12.9"
北緯24°35'07.1"，東經121°52'07.4" (WGS84)

海圖 0351A - 04515 - 04516

局長海軍上校孫永大公出
副局長海軍上校程國峰代行

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Oct-7-2019

49 Nanfang'ao Fishery Harbor – Correction to the Chart NMOO

Source 1. Maritime and Port Bureau, MOTC, notice to mariners dated October 1, 2019.
2. Naval Meteorological & Oceanographic Office, R.O.C., bathymetry information is updated on October 3, 2019

Details 1. The bathymetry information is updated due to collapsed bridge in Nanfang'ao fishery harbor on October 1, 2019.
2. Patches for chart amending to be pasted on related chart (0351A).
3. Mark the 「Precautionary area」 on related charts. (04515 & 04516).


Symbol  (Chart 04515 & 04516) 24°35'10.9"N., 121°52'07.4"
24°35'10.9"N., 121°52'12.9"
24°35'07.1"N., 121°52'12.9"
24°35'07.1"N., 121°52'07.4" (WGS84)

Chart affected 0351A - 04515 - 04516

CAPT. Kuo-Feng, Cheng
for CAPT. Yung-Da Sun
Commanding Officer, NMOO