



海軍大氣海洋局航船布告

中華民國108年1月30日

- 5** 林口發電廠 — 燈標修訂暨燈浮故障
- 依據 1. 台灣電力股份有限公司林口發電廠107年12月13日電子郵件。
2. 108年1月16日林口字第1088005675號函。
- 說明 1. 林口發電廠燈標修訂。
2. #1燈浮故障，修繕完畢後另行通知，航經該水域船隻，請注意安全。
- 位置 詳如附件。
- 海圖 0355 - 04512
- 刊物 燈表 106年第十一版(刊物第五種)，編號如附件。
- 參考布告 107年第52號航船布告。

海軍大氣海洋局局長
海軍上校 孫永大

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Jan-30-2019

- 5** Linkou Power Plant – Light Amended and Buoy Damaged
- Source 1. Linkou Thermal Power Plant, Taiwan Power Company, e-mail dated December 13, 2018.
2. Linkou Thermal Power Plant, Taiwan Power Company, letter No.1088005675 dated January 16, 2019.
- Details 1. The details of the lights, located in Linkou Thermal Power Plant, have been amended.
2. #1 light-buoy had stopped functioning, and a further notice will be issued while fixed.
- Position See attachment.
- Chart affected 0355 - 04512
- Publication affected Pub. No.5 List of Lights (Edition 11, 2017), light No. as attachment.
- Reference Former Notice 52/2018.

CAPT. Yung-Da Sun
Commanding Officer, NMOO

中華民國燈表 (List of Lights)

編號 No.	燈名 Name	位置 Position 北緯(Lat. N) 東經(Long. E) (WGS84)	燈質及光力 (燭光) Characteristics & Candle Power (candelas)	高度 高潮面起 (公尺) Elevation above HW (meter)	見距 (浬) Range (mile)	構造及高度 (公尺) Structure & Height (meter)	附註 Remarks, for signals, sectors
10874 (修正)	林口電廠北防波堤燈塔(PH1)	25 08 09.2 121 17 12.7	綠閃光 5 秒 明 1.0 秒;暗 4.0 秒 Fl.G.5s 1.0sL & 4.0sD		12.0	20.0	
10875 (修正)	林口電廠導流堤末端警示燈(PH2)	25 08 03.2 121 18 05.2	黃閃光 5 秒 明 1.0 秒;暗 4.0 秒 Fl.Y.5s 1.0sL & 4.0sD		8.0	20.0	
10876 (修正)	林口電廠前疊標(T1)	25 07 32.9 121 17 48.3	綠定光 F.G.		12.0		
10877 (修正)	林口電廠後疊標(T2)	25 07 27.9 121 17 55.1	綠定光 F.G.		12.0		
10881 (新增)	林口電廠海上燈浮#1	25 08 18.3 121 16 53.9	綠閃光 3 秒 明 1.0 秒;暗 2.0 秒 Fl.G.3s 1.0sL & 2.0sD		7.0		
10883 (修正)	林口電廠海上燈浮#3	25 08 00.1 121 17 19.1	綠閃光 3 秒 明 1.0 秒;暗 2.0 秒 Fl.G.3s 1.0sL & 2.0sD		7.0		
10884 (修正)	林口電廠海上燈浮#4	25 07 51.2 121 17 14.2	紅閃光 3 秒 明 1.0 秒;暗 2.0 秒 Fl.R.3s 1.0sL & 2.0sD		7.0		
10885 (修正)	林口電廠海上燈浮#5	25 07 49.5 121 16 52.3	黃閃光 5 秒 明 1.0 秒;暗 4.0 秒 Fl.Y.5s 1.0sL & 4.0sD		7.0		
10886 (修正)	林口電廠海上燈浮#6	25 07 45.9 121 17 19.6	黃閃光 5 秒 明 1.0 秒;暗 4.0 秒 Fl.Y.5s 1.0sL & 4.0sD		7.0		
10887 (修正)	林口電廠海上燈浮#7	25 07 37.2 121 17 28.7	黃閃光 5 秒 明 1.0 秒;暗 4.0 秒 Fl.Y.5s 1.0sL & 4.0sD		7.0		
10888 (修正)	林口電廠海上燈浮#8	25 07 37.1 121 17 42.9	黃閃光 5 秒 明 1.0 秒;暗 4.0 秒 Fl.Y.5s 1.0sL & 4.0sD		7.0		
10889 (修正)	林口電廠海上燈浮#9	25 07 49.0 121 17 56.1	黃閃光 5 秒 明 1.0 秒;暗 4.0 秒 Fl.Y.5s 1.0sL & 4.0sD		7.0		