



海軍大氣海洋局航船布告

中華民國110年5月5日

74 (暫) 基隆港 — 雷達標杆暫停播發信號

依據 交通部航港局110年5月3日第20210184號航船布告。
說明 1. 基隆港東外防波堤雷達標杆暫停播發信號，修復後另行通知，航經該水域船隻請注意安全。
2. 欲知修復進度，請逕洽交通部航港局航安組(電話：02-89785541)。
位置 北緯25°09'50.5"，東經121°45'14.4" (WGS84)
海圖 0353 - 0353A
刊物 中華民國燈表(109年第12版，刊物第五種)，編號：11280

海軍大氣海洋局局長
海軍上校 孫永大

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

May-5-2021

74 (T) Keelung Port – Radar Beacon (Racon) Temporarily Stop Functioning

Source Maritime Port Bureau, MOTC, notice to mariners No.20210184 dated May 3, 2021.
Details 1. E. outer breakwater radar beacon (racon), located in Keelung port, temporarily stopped functioning. Further information will be issued while fixed. Mariners should navigate with caution in this area.
2. Contact to the Maritime Safety Division (Tel:886-2-89785541) for the latest information.
Position 25°09'50.5"N., 121°45'14.4"E. (WGS84)
Chart affected 0353 - 0353A
Publication affected Pub. No.5 List of Lights (Edition 12th, 2020), No. 11280

CAPT. Yung-Da Sun
Commanding Officer, NMOO